
NATIONAL LABORATORY

April 9, 2001

date:

Building 911A P.O. Box 5000 Upton, NY 11973-5000 Phone 516 344-7343 Fax 516 344-5676 maraviglia@bnl.gov





## Memo

to:	BRAHMS Shift Leaders
from:	J. Maraviglia
subject:	Read & Acknowledgement of Selected C-A Dept Procedures
	S Shift Leader, part of your training requirements is to familiarize yourself with certain elerator Department (C-AD) procedures.
	rize yourself with the C-AD OPMs hyperlinked below. Complete the bottom portion of I return to Ann Marie Luhrs, Bldg 911A.
If you have an (631) 344-734	y questions or comments contact your BRAHMS liaison physicist, or I can be reached at 3.
<u>C-A OPM 2.5</u>	.2 RHIC Accelerator Safety Envelope Parameters
<u>C-A OPM 3.1</u>	9 Emergency Procedures for BRAHMS Detector Building 1002 Complex
<u>C-A OPM 11.</u>	1 Policy for Conduct of Operations for the RHIC Experiment Shift Leaders
NAME	/